

BV: Pelzerhaken - Fassadensockelsanierung

Haus C Pamir - Aufmaß

Haus H Lord Nelson- Aufmaß

Flächen-Nr.	Oberdeckel	Unterdeckel	Sockel	Fensterbank	Bordstücke
	Stck	Stck	in m	in m	in Stck
1	12	13	3,085	3,141	2
2	21	23	6,366	5,300	3
3	10	12	4,686	2,541	4
4	14	17	5,185	3,675	5
5	18	21	5,960	4,585	6
6	12	13	3,150	3,150	3
7	19	19	5,235	4,105	5
Seiten Nr.	106	118	33,667	26,497	28

Schalung 22 x100 mm Pos. 12

Seiten Nr.	Stck	lfdm	Gesamt
1	2	3,141	6,282
2	2	5,300	10,6
3	2	2,541	5,082
4	2	3,675	7,35
5	2	4,585	9,17
6	2	3,150	6,3
7	2	4,105	8,21
Gesamt			52,994

Lüftungsgitter

Seiten Nr.	Stck
1	2
2	2
3	2
4	2
5	3
6	3
7	2
Gesamt	16

Seiten Nr.	x Zusätzliches Material	Oberdeckel	lfdm	Gesamt
1	Oberdeckel 190	3	1,57	4,71
Gesamt				4,71

Oberdeckel in m:

Einzellänge	0,53	
in m		56,18
Verschnitt in Prozent	15%	8,427
in m		64,607

Unterdeckel in m:

Einzellänge		
in m		
Verschnitt 15%		
in m		

Sockel in qm

Sockelhöhe		
in m	0,35	11,7835
	80%	11,7835
Verschnitt	20%	2,9459
in qm		14,7293

Fensterbank in m

Fensterbank		26,497
Verschnitt 10%		2,6497
in m		29,1467

Schalung 22x100

Schalung inkl. Verschnitt

in m		52,994
Verschnitt	10%	5,2994
in m		58,293

190 x 23 x 1560 getauscht

Hs. C Pamir

1

2 Bod

2 Gills



2



3300

2610

2000

1066

3300

Dachel 24
Unter 23



Hs. C Pamir



5 Bern

26/11/01
C

Deck 24
Vint 18

Hs. C Pamir



15

6 Bord
3 Gitter.

Deckel 18
Unter 21

Hs. C Pamir

6



3 Bord

36' Her

3150

D. Ad 12

C. Ad 13

Hs. C Pamir



(X)

5 Bsq
26/16

Deck 4.6
Winter 19