




Läken Tischlerei & Fenstertechnik GmbH	Liefertermin: 23.06.23	Blatt Nr. 1
AU: 58714 Leda Werk GmbH & Co. KG // Kom:Sanierung Leer, Verwaltung 1 OG-P1		21.04.23




Auftrag : 58714 ()
Pos. : 1.1 ()
Stück : 1
969.0 mm x 1214.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=1200
 [GP 124* GP 124]



Auftrag : 58714 ()
Pos. : 2.1 ()
Stück : 1
944.0 mm x 1189.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=1282
 [GP 124* GP 124]




Auftrag : 58714 ()
Pos. : 3.1 ()
Stück : 1
809.0 mm x 1154.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=1300
 [GP 124* GP 124]




Auftrag : 58714 ()
Pos. : 4.1 ()
Stück : 1
964.0 mm x 1209.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=1189
 [GP 124* GP 124]


Läken Tischlerei & Fenstertechnik GmbH	Liefertermin: 23.06.23	Blatt Nr. 2
AU: 58714 Leda Werk GmbH & Co. KG // Kom:Sanierung Leer, Verwaltung 1 OG-P1		21.04.23




Auftrag : 58714 ()
Pos. : 5.1 ()
Stück : 1
949.0 mm x 1214.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=1245
 [GP 124* GP 124]



Auftrag : 58714 ()
Pos. : 6.1 ()
Stück : 1
964.0 mm x 1184.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=1278
 [GP 124* GP 124]




Auftrag : 58714 ()
Pos. : 7.1 ()
Stück : 1
844.0 mm x 1089.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=920
 [GP 124* GP 124]



Auftrag : 58714 ()
Pos. : 8.1 ()
Stück : 1
964.0 mm x 1204.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=1189
 [GP 124* GP 124]

Läken Tischlerei & Fenstertechnik GmbH	Liefertermin: 23.06.23	Blatt Nr. 3
AU: 58714 Leda Werk GmbH & Co. KG // Kom:Sanierung Leer, Verwaltung 1 OG-P1		21.04.23



Auftrag : 58714 ()
Pos. : 9.1 ()
Stück : 1
834.0 mm x 1084.0 mm
 Wärmesch. Ug 1.2 - 4/20/4
 SZR = 0
 Radius=1084
 [GP 124* GP 124]